LOCATION Fredericktown, PA

PROBLEM

An existing 1200' – 6" ductile iron pipe anchored in the bottom of a river was creating too many disruptions in service.

SOLUTION

- The water company decided to change out the line using 6" HDPE pipe.
- Flexible HDPE pipe was fused on the barge on the river surface. Then concrete anchors were attached to it.



IMPACT TO CUSTOMER

- The fusion of the HDPE provided "leak-free" connections and the smooth interior of HDPE provided a slight increase in the volume.
- By using "controlled sinking" to drop the pipe into the river, it eliminated costly underwater installation.

	QUALITY	PEOPLI	E PRODU	JCTS S	ERVICE	Since 1954
	PENNSYLVANIA		SOUTH CAROLINA	VIRGINIA	WEST VIRGINIA	www.leesupply.com
SUPPLY CO. INC.	CORPORATE OFFICE CHARLEROI 800-353-3747	McElvenny Division Downingtown 610-518-5499	West Columbia 803-476-7348	Coeburn 888-353-3747	Shady Spring 888-353-3747	
24-HOUR EMERGENCY SERVICE TEL: 724-483-7035 (after 5pm, evenings & weekends)						
						7953_MUN04

WATER CROSSING