

PROBLEM

- A deteriorated 24" reinforced concrete sewer line
- Project site included contaminated soil which could not be disturbed

SOLUTION

- Lee Supply provided on-site certified fusion technicians and a trailer including:
 - large diameter McElroy fusion equipment (from our rental fleet)
 - all necessary inserts for the different size pipes
- Only three access pits were required
- During the pipe bursting process a percussion head was used to fracture the pipe
- An expander head eliminated the remains of the existing line allowing 1400' of 32" HDPE pipe to be pulled through



IMPACT TO CUSTOMER

- The community got a sewer line with increased flow for future services with little to no disturbance of the environmentally sensitive area



QUALITY PEOPLE PRODUCTS SERVICE Since 1954

PENNSYLVANIA		SOUTH CAROLINA	VIRGINIA	WEST VIRGINIA	www.leesupply.com
CORPORATE OFFICE CHARLEROI 800-353-3747	McElvenny Division DOWNTOWN 610-518-5499	WEST COLUMBIA 803-476-7348	COEBURN 888-353-3747	SHADY SPRING 888-353-3747	



24-HOUR EMERGENCY SERVICE TEL: 724-483-7035 (after 5pm, evenings & weekends)