

**LOCATION** Mingo Junction, OH

**COMPLETE THE CIRCUIT**

**PROBLEM**

- Contaminated water from the "BOF" cooling system is recycled from the treatment plant to the furnace in a complete circuit requiring various fittings and a substantial amount of pipe.

**SOLUTION**

- Lee Supply field technicians measured and fabricated an 18" HDPE lateral, other fittings and pipe to specification.

**IMPACT TO CUSTOMER**

- New material reduces the need for frequent repair and replacement
- Withstands corrosive slurry



QUALITY



**QUALITY PEOPLE PRODUCTS SERVICE** *Since 1954*

| PENNSYLVANIA   |   | SOUTH CAROLINA                | VIRGINIA                | WEST VIRGINIA                | <a href="http://www.leesupply.com">www.leesupply.com</a> |
|--|---|-------------------------------|-------------------------|------------------------------|--|
| <b>CORPORATE OFFICE</b><br>CHARLEROI<br>800-353-3747 | <b>McElvenny Division</b><br>DOWNTOWN<br>610-518-5499 | WEST COLUMBIA<br>803-476-7348 | COEBURN<br>888-353-3747 | SHADY SPRING<br>888-353-3747 |  |



**24-HOUR EMERGENCY SERVICE** TEL: 724-483-7035 (after 5pm, evenings & weekends)